



**AUM SAI INSTITUTE OF TECHNICAL EDUCATION**

**MANUFACTURING TECHNOLOGY**  
**LECTURE NOTES**

Prepared by  
**ER.RABINDRA DASH**

**DEPARTMENT OF MECHANICAL ENGINEERING**

There are many types of cutting process done in different condition. In such condition along with the general requirement of the cutting tool, they need some unique properties. To achieve these properties the cutting tool are made up of different materials. The material chosen for a particular application depends on the material to be machined, type of machining, quantity & quality of prod<sup>n</sup> etc.

According to the material the tools are

classified into

1. Carbon tool steel
2. High speed steel (HSS)
3. Cymantite carbide
4. Ceramics tools
5. Cubic boron nitride tool (CBN)
6. Diamond tool

1. Carbon tool steel:-

→ Its temperature range from 250°C.  
→ It is one of the inexpensive metal cutting tool used for the low-speed machining operation.

→ This carbon steel cutting tool have the composition 0.6 - 1.5% Carbon & very small amount of (less than 0.5%) Mn & Si.

→ High carbon steel have the ability to maintain sharp cutting edge & it possess good machinability.

→ It doesn't perform in a modern & machining operation.

→ Carbon tool steel used in drill, reaming tool, turning use on those material such as brass, Al, Mg etc.

## 2. High Speed Steel:-

- This is a high carbon steel with a significant amount of alloying elements such as tungsten, Mo, Cr etc. to improve hardenability, toughness & wear resistance.
- It gives a higher metal removal rate & it loses its hardness at a moderate temperature about 650°C. Therefore a coolant should be used to increase tool life.
- It can use many time by re-sharpening some further & treatment is done on the HSS to improve its properties.

Surface treatment used in HSS:-

Superfinishing - reduce friction

Nitriding - increase wear resistant

Chromium electro plating - reduce friction

Oxidation - reduce friction

→ It is used in drill, reaming, turning centers, single point lathe tool.

Ti type - Tungsten predominant type

M type - Mo predominant type

## 3. Cementite carbide tool:-

- It is produced by powder metallurgy technique.
- It consists of tungsten, tantalum & titanium carbide with cobalt as a binder (when the binder is only Mo then it is used Cermet).
- Cementite carbide tool are extremely hard, they can withstand very high speed cutting operation.
- It doesn't lose their hardness upto 1000°C.
- A high cobalt tool is used for a rough cut while low cobalt is used for finishing operation.

## 4. Ceramics:-

### 1. Ceramics:-

- The most common ceramic material are alumina oxide ( $Al_2O_3$ ) & Silicon nitride. Powder of ceramic material compacted in insert shape, then sintered at high temperature.
- Ceramic tools are chemically inert pass resistant to corrosion.
- They have high compressive strength, they are stable upto temperature 1800°C.
- They are 10 times harder than HSS.
- The friction coeff. tool back chip are very low & pores low heat conductivity, usually no coolant is required, they provide a very excellent surface finish.

### 5. CBN's

- It is the second hardest material after diamond.
- They are generally used in hand machine.
- They offer high resistance to abrasion & wear & abrasive in grinding wheels.
- Sharp edges are not recommended.

### 6. Diamond's

- It is the hardest material & it is also expensive.
- It possess a very high thermal conductivity & M.P.
- The diamond occurs a excellent abrasion & excellent low friction co-efficient & low thermal expansion.
- It is used in machining very hard material such as Carbides, nitrides, glass etc.
- Diamond tools give a good surface finish & dimensional accuracy.
- They are not recommended for machining brittle materials or cutting tool materials.

→ Cutting tool materials are the materials used to make cutting tools which are used in machining. (drill bits, tool bits, mining cutters etc.) but not with other cutting tools like knives & punches.

→ Cutting tool materials must be harder than the material or work piece, even at high temperature during the process:

→ The following properties required for cutting tool

1. Hardness, heat hardness & pressure resistance.
2. Bending strength & toughness.

### 11. Inner bonding strength

### 12. Wear resistance

- a. edge resistance
- b. edge strength
- c. Small porosity for diffusion & adhesion.

There is no material that should all of the properties at the same time.

Tool material	Cutting speed	Temperature (°C)	Hardness
Carbon tool steel		450°C	up to HRC 65
HSS (30-50 m/min cutting range)	30-50 m/min	650°C	up to HRC 67 30-50 m/min
Cementite Carbide	60-200 m/min	1000°C	up to HRC 90
Ceramic	300-600 m/min	1200°C	up to HRC 92
CBN	600-800 m/min	-	up to HRC 95
Diamond		600°C	

the High superhard capacity

## Chapter - 2 :- Cutting Tools :-

Cutting action of various tools :-

### 1. Chisel :-

A chisel is a tool with a characteristically shaped cutting edges (such that wood chisel have part of their name to a particular grind) of blade on its end, for carving or cutting hard material such as wood, stone or metal by hand, struck with a mallet or mechanical power. The handle & blade of some types of chisels are metal or wood with a sharp edge with it.

Cutting angle of chisel :-

The angle which is usually set to  $25^\circ$  is called grinding angle as the chisel ground down to this angle when blunt made. The second angle (usually  $35^\circ$ ) is called a cutting angle & allows for region sharpening of the chisel & set.

### 2. Hacksaw :-

A hacksaw is a fine tool to saw originally & mainly made for cutting metal. (The equivalent saw for cutting wood is usually saw saw) most hacksaw are hand saw with a 'c' clamp blade that holds a blade under tension, such hacksaw have a handle usually a piston gripper, with pin for attaching narrow disposable blade. The frames may also be adjustable to accommodate blade of different size. A screw on

other mechanism is used to put the blade under tension.)

on hacksaw, as it's most frame, teeth & the blade can be oriented with the teeth facing towards or away from the handle resulting in cutting action on either push or pull stroke. (As normal use cutting vertically downwards which works held in bench vice, - hacksaw blade are set to be facing towards)

### 3. Dies :-

→ Cutting die used to cut the metal to utilize the cutting or shearing action.

→ The common dies are notching, forming, shearing, blanking etc.

→ Die cutting is typically reverse the cutting action of a die cast.

→ Die cutting tooling is fundamentally a comb<sup>2</sup> or wood steel blade & rubber prepared into a specific stack structure to enable compression of lubricated material hence having a specific shape.

Different types of dies using in sheet metal :-

Compound die, multiple die

Comb<sup>2</sup> die, progressive die.

What does a die do? :-

A die is used to cut or form the male portion of the mating pair (A or a half). The process of cutting or forming thread using a tap is called tapping whereas the process using a die is called threading.

How does a die work?

- Tapping is when threads are cut into a cylinder (hole).
- To use a tap or a die, first determine the no. of threads per inch (TPI) of the part to be bired.
- A gauge system that has a no. of different pins is to be used to calculate the TPI of the bolt or nut.

Advantage :-

Die cutting yields a level of uniformity or a final product i.e. almost unmatched.

Die

4. Reamer :-

→ The main cutting action of reamer is done by straight taper, the sizing action is to guide the reamer & also smooth or size the hole.

→ The back taper reduces friction between reamer & hole surface.

Function :-

→ A reamer is a type of rotary cutting tool used in metal working precision reamed.

→ Reamers are design to a large size <sup>other than</sup> ~~or~~ previously born hole by small amount but a high degree of

Why are reaming operation performed :-

- Reaming performed using same type of machine like drilling.
- Reamer is a rotary cutting tool with one or more cutting elements use to enlarge size & to control the previously hole.
- It's principle support & guiding cutting action of the work piece.

Reamers 4 types :-

- ↳ Hand reamer
- ↳ Machine reamer
- ↳ Chucking reamer
- ↳ Fluting reamer
- ↳ Expandable reamer
- ↳ Slapper reamer
- ↳ Adjustable reamer

What is tool geometry :-

→ Geometry of a cutting tool <sup>are</sup> the chip angle by which the cutting portion of a cutting tool are ground.

→ It influence (or) the type of machining process, the material, the efficiency & economy, the quality of the finished part, & the life of <sup>the</sup> cutting tool.

What is tool angle :-

The angle included between the top & front faces of the tool on an angle view to designate the form of a cutting edge of a tool.

### Tool geometry of turning tools:-

→ Both material & geometry of the cutting tool play very important role on their performance on achieving effectiveness, efficiency and overall economy of machining.

→ Cutting tool may be classified according to the no. of major cutting edges (points) involve as follows.

#### i. Single point tool

Ex: turning tool, shaping, planing & slitting

#### ii. Boring tool

#### iii. Double point

Ex: Drill

#### iv. Multipoint (more than two)

Ex: milling cutter, broaching etc.

### Concept of rake angle of cutting tool:-

⊕ Rake angle is provided for each of chips blow & overall machining.

→ Rake angle may be positive or negative or even zero.

### Concept of clearance angles of cutting tool:-

→ Clearance angle is essentially provided to avoid rubbing of the tool with the machine surface which cause loss of energy & damage of both the tool & the job surface.

→ Hence the clearance angle is a must & must be positive ( $3^\circ$  to  $15^\circ$ ) depending upon the tool work material

& type of machining operations like turning, drilling & boring etc.

### Terminology of single point cutting tool:-

#### Rake

#### Back rake angle

→ It viewed the side facing the end of the work piece it is the angle form by the back of the tool & line parallel to the floor.

→ A positive back rake angle flip the tool base back, a negative back rake angles flip

it forward & up.

#### End cutting edge angle:-

→ It viewed a from above looking down at the cutting tool, it is the angle formed by the end flank of the tool & the line parallel to the work piece centerline.

#### End relieve angle:-

It viewed from the side facing the end of the work piece, it is the angle formed by the end flank of the tool & a vertical line down to the floor.

#### Face:-

The flat surface of a single point tool into which the work piece rotates during a turning

operations.

Flank:-

A flat surface at a single point tool i.e. adjacent to the face of the tool. During turning the side flank faces the direction that the tool is fed into the workpiece & the flank panel over the newly machined surface.

Lead angle:-

→ A common name for the side cutting edge angle. If a tool holder is built with dimension that keep the angle of an insert, the lead angle takes this change into consideration.

Side rake angle:-

It is the angle formed by the face of the tool & the center line of the work piece.

Side relief angle:-

It is the angle formed by the side flank of the tool & a vertical line down to the floor.

Note radius:-

→ The rounded tip of the cutting edge of a single point tool.

→ The greater the nose radius, the greater the roundness of the tip.

→ A zero degree nose radius creates a sharp point

Side cutting edge angle:-

It is the angle formed by the side flank of the tool & a line perpendicular to the work piece centerline.

Process parameter:-

→ For any machining or metal cutting operation three relative motion bet<sup>n</sup> the work piece & the cutting tool are necessary for gradual removal of material from work piece. In fact, the simultaneous action of all three relative motion causes advancement of cutting tool towards work material along the path generating a finish surface with the shape, size & tolerance.

→ This three relative motion are called cutting parameters.

→ The process parameter in machining all those parameter that inherent to a any machining operation & should have a suitable finite value to smooth & efficient removal of material. Each parameter directly effect machining operation.

→ In machining three parameters are

1. Cutting speed or cutting velocity

2. feed rate


3. depth of cut



### 1. Cutting velocity: ( $V_c$ )

→ It is the most important cutting parameter that provide necessary cutting motion. In case of either rotating tool such as milling, drilling & grinding etc. or rotating workpiece such as turning, the peripheral vel. of cutter or workpiece is considered as cutting velocity. The rotational speed is called cutting speed whereas the tangential velocity is called cutting velocity.

→ It is denoted by  $V_c$ .



### 2. Feed rate: ( $f$ )

→ The auxiliary cutting motion, it provided by the feed rate or feed velocity.  
 → usually the dir<sup>n</sup> of feed velocity, is perpendicular to that of the cutting velocity. The primary objective

of feed velocity is to advance cutter with the workpiece to remove material from a wider surface.

→ Basically it helps in covering the entire surface of the workpiece by moving either cutting tool or workpiece.

### 3. Depth of cut ( $d$ ):

→ The tertiary cutting motion that provides necessary depth with in work material i.e. intended to remove by machining.

→ It is given in the third & perpendicular dir<sup>n</sup> to the simultaneous action of three cutting parameters result in removal of excess material from workpiece.

### Features or process parameters:-

It must be,

- a primary factor i.e. there shouldn't be any other factor that control it.
- It must be supplied during machining.
- It should have a finite value.
- It should directly effect machining performance.
- It can be varied externally without changing the work tool combination.

Process parameter different from influencing parameters:-

→ Influencing parameters include all those parameters that can directly or indirectly influence the machining operations thus all process parameters are influencing parameters apart from velocity, feed & depth of cut, there are many other parameters that can influence performance considerably, however they are not inherent to machining process.

→ A list of such parameters relevant to conventional machining:

- i. Cutting environment
- ii. Tool geometry including nose radius.
- iii. work material
- iv. Tool material.
- v. Tool coating
- vi. work and tool setting.

Coolant and lubricant in machining

The basic purpose of coolant is to take away generated cutting heat from cutting zone; and thereby keep the cutting zone temp. low. The basic purpose of lubricant is to reduce coefficient of friction bet<sup>n</sup> rake surface of cutting chip and thereby minimize heat generation.

3. Straight oil (petroleum or vegetable oil)

4. Synthetic fluids

5. Semi synthetic fluids

→ What are the three main properties of lubricant?

1. Prevent seizing & boiling

2. Lubricates the water pump seal.

10. Inhibits corrosion

What are the different types of lubricant?

→ There are 3 different types of lubrication.

1. boundary

2. mixed

3. full film

→ Each type is different but they all rely on lubricant and the additive with in the oil to protect against wear.

→ Full film lubrication can be broken down into two forms

1. Hydrodynamic

2. Elasto hydrodynamic

What are some examples of lubricant?

→ Lubricant include fatty alcohols, esters & wax etc.

→ External lubricant provides metal release & help to reduce temperature.

→ The common examples of external lubricant

i. Paraffin

ii. metal soap.


iii. Amide

iv. Fatty acid




Each coolant a lubricant?

→ Cutting fluid is a coolant that also serves as a lubricant for metal shaping machine tools.

→ Oils are often used for application where water is unavailable.



- $\alpha_b$  - Back rake angle
- BR  $\alpha_s$  - Side rake angle
- SR  $\theta_c$  - End relief angle (clearance)  $\theta_c$   $\theta_c$
- $\theta_s$  - Side relief angle
- $\phi_e$  - End cutting edge angle (ECEA)
- $\phi_s$  - Side cutting edge angle (SCEA)



## Construction & working of lathe & CNC lathe.

### Definition of lathe machine :-

- A machine tool that is used to remove unwanted metal from the work piece to give the desired shape and size is called 'lathe machine'.
- It is also called as centre lathe because on two centres b/w which the job can be held & rotated.

### Functions of lathe :-

- Main function of lathe is to remove excess material in the form of chips by rotating the workpiece against a stationary cutting tool.
- To cut the material properly the tool should be harder than the material of the work piece.

### Main parts of lathe machine :-

#### 1. Bed :-

- It is the base of the lathe machine made up of single piece casting of cast steel (or cast iron).
- The bed consists of two heavy metal slides running lengthwise with 'V' turned on them and rigidly supported with cross feeds.

#### functions :-

- It is sufficiently rigid and good damping capacity to absorb vibration.
- It prevents the deflection produced by the cutting forces.
- It supports the headstock, tailstock, carriage and other components of the lathe machine.

#### 2. Head Stock :-

Head stock is situated at the left end of the lathe bed and it is the house of the driving mechanism and electrical mechanism of a lathe machine tool.

#### functions :-

- It holds the job on its spindle nose having external screw threads and internally mount tapered bar holding the lathe center and it is rotating at a different speed by cone pulley or a geared drive. There is a hole through out the spindle for handling long bar work.
- Head stock transmits power from the spindle to the bed tool, lead screw & thread cutting mechanism.

Accessories mounted on headstock spindle :-

① Three jaw chuck

② Four jaw chuck

③ Lathe center & lathe dog

④ collet chuck

⑤ face plate

⑥ magnetic chuck

#### Note :-

→ A separate speed change gearbox is placed below headstock to reduce the speed in order to have different bed tools for threading & automatic lateral movement of the carriage.

→ The bed tool is used for most turning operations and the lead screw is used for thread cutting operation.

### 3. Tail Stock

Tail Stock is situated on the right side above the lathe bed.

Functions:-

- Support the long end of the job for holding & minimize its sagging.
- It holds the tool bar performing different operations like drilling, reaming, tapping etc.
- Used for a small amount of taper on a long job by offsetting the tail stock.

### 4. Carriage

→ It is located b/w headstock & tail stock on the lathe bed guide ways.

→ It is used to support, guide & feed the tool against the job when the machining is done.

Functions:-

- It holds, moves & control the cutting tool.
- It gives rigid supports to the tool during operations.
- It transfers power from feed rod to cutting tool through apron mechanism for longitudinal cross feeding.
- It simplifies the thread cutting operation with the help of lead screw & half-nut mechanism.

It consists of

- Laddle
- Cross-slide
- Compound rest
- Tool post
- Apron
- Compound slide

It provides three movements to the tool

- Longitudinal feed - through carriage movement
- Cross feed - through cross slide movement
- Angular feed - through top slide movement

### (i) Laddle :-

→ It is 'L' shaped casting

→ It connects the pair of bed guide ways as a bridge

→ It sits over the bed and slides along the bed b/w head stock & tail stock.

### (ii) Cross slide :-

→ It is assembled on the top of the laddle.

→ The top surface of the cross slide is provided with T-slot.

→ The cross slide hand wheel is graduated on full rim to enable to give known amount of feed as accurate as 0.05 mm.

### (iii) Compound Rest :-

→ It is a part which connects cross slide and compound slide.

→ It is mounted on the cross slide by using one groove in it.

Functions:-

→ It supports the tool post and cutting tool, in various position.

→ It is necessary for turning angles and bearing short tapers.

### (iv) Tool post :-

It is the topmost portion of the carriage and it is used to hold various cutting tools on tool holder.

## Types :-

- Single way / cross tool post
- Four way tool post
- Quick change tool post
- British type tool post

## (V) Apron :-

→ It is the house of the feed mechanism.  
→ It is fastened to the saddle & hangs over in front of the bed.

## (VI) Compound slide :-

It is a T-shaped rounded flat, which is fixed with cross slide upper limb by two bolts, which is related to a micrometer sleeve & screw handle with the outer edge of screw.

- This slide is only used for long job taper turning.
- Automatic feed is not possible in compound slide.

## 5. Main spindle :-

It is a hollow cylindrical shaft in which long tools can pass through.

- Its base has a standard Morse taper.
- It is used for holding the live centers.
- The spindle rotates on two large bearings fixed on the head stock casting.

## 6. Lead screw :-

- It is used to transmit power to carriage through gear and clutch arrangement in the carriage apron.
- It converts rotational motion into linear motion.
- It is used for thread cutting operation.

## 7. Live center :-

- It is mounted on bearings and rotates with the work.
- It is used to hold or support a work piece.

## 8. Dead center :-

- It is used to support the work piece at either the fixed or rotating end of machine.

### Functions :-

Dead centers are typically fully hardened to prevent damage to the important mating surfaces of the taper and to preserve the 60° angle of the nose.

## 9. Feed rod :-

fun<sup>n</sup> :- It is used to move the carriage from the left side to the right side and also from the right side to the left side.

## 10. Chuck :-

fun<sup>n</sup> :- It is used to hold the work piece securely.

### Types :-

- 3 jaw self-centering chuck
- 4 jaw independent chuck

## 11. Leg :-

- fun<sup>n</sup> :- Leg carries the entire load of a lathe machine tool and transfer to the ground.
- The legs are simply secured to the base by the foundation bolt.

Working principle of lathe machine

Working principle :-

- > The lathe is a machine tool which holds the workpiece between rigid and strong supports called centers or in a chuck on one plate which revolves. The cutting tool is rigidly held and supported in a tool post which is fixed against the revolving work.
- > When the cutting tool is fed parallel to the workpiece a cylindrical surface is formed.
- > When the cutting tool is fed at an angle relative to the axis of the workpiece, it produces a tapered surface and also called as taper turning.




Lathe operation :-

The engine lathe is an accurate & versatile machine on which many operations can be performed, which are as follows:-

① Plain turning / deep turning :-


Plain turning :-

It is the operation of removing excess amount of material from the surface of a cylindrical job.



Step turning :-

It produces various steps or different diameters.




② Facing :-

It is a machining operation by which the end surface of the workpiece is made flat by removing metal from it.



③ Parting :-


Parting or cutting off is the operation of cutting away a desired length of the workpiece.



④ Drilling :-


Drilling is the operation of producing a cylindrical hole in the work piece.






⑤ Reaming :-

The holes that are produced by drilling are rarely straight & cylindrical in form. The reaming operation finishes & sizes the hole already drilled into the workpiece.




⑥ Boring :-

It is the process of enlarging a hole already produced by drilling.




⑦ Knurling :-

→ It is a process of impressing a diamond-shaped or straight line pattern into the surface of workpiece.  
→ It is essentially a roughening of the surface and is done to provide a better gripping surface.




⑧ Grooving :-

It is the operation of making grooves of reduced diameter in the workpiece.



⑨ Threading :-


It is the operation of cutting of the required form of threads on the internal & external cylindrical surfaces.



20/4/8 23:29

### 10) Forming :-

It is an operation, which produces a convex, concave or irregular profile on the workpiece.



### 11) Chamfering :-


- Chamfering removes the sharp edges and rough edges and makes the handling ease.
- Chamfering can be done by a form tool having angle equal to chamfer which is generally kept at 45°.

### 12) Filing and polishing :-

- Filing is the finishing operation that removes rough edges, sharp corners and feed marks from the workpiece.
- After filing, the surface quality of the workpiece is improved by polishing operation.

### 13) Taper turning :-

It is the operation of producing a conical surface by gradual reduction in the diameter of a cylindrical workpiece.



### Safety measures during machining :-

- Always stop the lathe before making adjustment.

#### → General

- Do not change spindle speeds until the lathe comes to a complete stop.
- Always wear protective eye protection.
- Never lay tools directly on the lathe ways. If a separate table is not available, use a wide board with a cleat on each side to lay on the ways.
- Use two hands when standing the workpiece. Do not wrap the sand paper or emery cloth around the workpiece.
- Remove rings and watches.
- Keep the floor free from obstructions or slip hazards.
- Follow job specification for the speed, feed & depth cut for materials being turned. Make sure all work is true and centered.
- Stop lathe before taking measurements of any kind.
- Keep working surface clean of scraps, tools & material.

#### Types of lathe machine :-

- 1) Center (or) engine lathe :-  
It is the most widely used lathe machine.  
Parts :- Bed, saddle, headstock & tailstock etc.  
→ The headstock of an engine lathe is rigid tailstock is movable which is never used in knurling.  
function :- It feeds the cutting tool in both directions i.e. longitudinal and lateral direction with the help of feed mechanism.

mechanism:-

Driven by gear mechanism or pulley mechanism.

Types or driven mechanism

- ① Belt driven
- ② Motor driven
- ③ Gear head type.

Turret lathe:-

It is a lathe form of metal working lathe is used repetitive prod<sup>n</sup> or duplicate parts which by the nature of their curing process usually interchangeable.

Capstan lathe:-

A Capstan lathe is a precision machine used to make the same parts again & again. The cutting bits are mounted on a rotatable turret known as capstan, which permits the client to rapidly change the insert the bit but being without needing to take off the first bit & bits used mount the second.

What is Capstan lathe used for?

→ A capstan or turret lathe is used to manufacture any no. of identical pieces in the minimum time.

→ These lathes are best developed in USA in 1960.

→ Capstan lathe is one of the type of semi automatic lathe.

What is turret lathe?

1. Ram type

2. Saddle type

1. Ram type:-

In the ram type turret lathe a slide or ram carrying the turret moves back & forth on a saddle which is clamp to the machine bed.

2. Saddle type:-

In this type the hexagonal turreted is rigidly mounted on saddle & the hole unit moves

back & forth on the bed ways.

What is swing of a lathe?

The swing of a lathe machine is actually the dimension that measures the max. diameter of the workpiece that a lathe is able to rotate with heating the bed.

diff. bet<sup>n</sup> capstan & turret lathe

Capstan	Turret
→ It is a light weight track	→ It is a heavy weight machine
→ In capstan lathe the turret tool head is mounted over the ram & is mounted over the saddle.	→ In turreted tool head is mounted over the saddle like a single unit.
→ For providing feed to the tool ram is moved.	→ For providing feed to the tool the saddle is moved.
→ because of no saddle displacement the moment of turret tool head over the longitudinal dir <sup>n</sup> of bed is less along the ram.	→ Turret tool head moved along with the saddle over the entire bed in longitudinal dir <sup>n</sup> .
→ Use for center workpiece bcz of limited ram movement.	→ Use for longer workpiece saddle movement on the bed.
→ In working operation are fast bcz of lighter construction.	→ In working operation are slower bcz of heavier construction.
→ Heavy cut on the workpiece can't be given bcz of non rigid construction.	→ Heavy cut on the workpiece is given bcz of rigid construction.

→ For indexing turret tool head of the ram is reverse & turret tool index automatically

→ The turret head can't be moved in the lateral dir<sup>n</sup> of the bed

→ In capstan lathe collet is used to grip the job

→ Use for machining work piece upto 60mm diameter

→ There are usually horizontal lathe.

→ For indexing turret tool head the turret is rotated manually after releasing the clamping lever.

→ The turret head can be moved crosswise i.e. the lateral dir<sup>n</sup> of bed.

→ In turret lathe power jaw chuck is used to grip the job.

→ Use for machining work piece upto 60mm diameter.

→ Turret lathes are available in horizontal & vertical.

### Engine lathe

→ An engine lathe is a type of machinery, built horizontally & it is often to use cut metal.

→ The metal is turned the machine uses special cutting tool to create the desired shape. because of the lathe, it can create various specific forms & commonly used to spin sheet metal.

difference bet<sup>n</sup> turret lathe & engine lathe.

Turret lathe are planned to act as production machine & engine lathe is planned machine various type of job within limits. i.e. one time setting is moved you mustn't change the tool.


### Diff bet<sup>n</sup> turret

### what is precision lathe?

Precision lathes are also known as standard manufacturing lathe & is used to do all lathe operation such as turning, taper turning, threading,reaming etc and can be adapted for special milling operation with the appropriate bitting

## Shaping machine or shaper


- A shaping machine or shaper is used to generate flat (plane) surfaces by means of a single point tool similar to a lathe tool.
- A shaping machine is a reciprocating type of machine.
- Tool involved: The ram moves the cutting tool backward & forward in a straight line.



### Process Capabilities:

- Shaping process involves short setup time & uses relatively inexpensive tools.
- Shaping is often used for emergency production of gears, racks etc.
- It is often possible to produce one <sup>copy</sup> of such parts in a shaper in less time than is required nearly to setup for production on other alternative equipment with a higher output rate.
- However, metal removal by shaping may be somewhat slower than removal by milling or grinding.

### Working principle:-



- The tool held in the tool holder mounted on the ram moves backward & forward in a straight line over the workpiece rigidly held in a vice clamped over the work table.
- Each time the tool moves forward, it cuts the metal from workpiece. Each time the tool moves backward the tool leaves clear of the workpiece.
- The work remains stationary during the forward (cutting stroke of the tool) but moves across by one cross transverse during the return (non cutting stroke).
- That the appearance of the machine surface is of a succession succession of closely straight line wave.

### Types of

2020/4/3 23:30

### Types of shaper :-

Shaper may be classified on the basis of

#### A) design of worktable :-

1. Standard shaper

2. Universal shaper

#### B) Driving mechanism :-

1. Crank shaper

2. Gear shaper

3. Hydraulic shaper

#### C) Direction of travel of ram :-

1. Horizontal

2. Vertical

3. Travelling hand shaper

#### D) Nature of cutting stroke :-

1. Push cut shaper

2. Draw cut shaper

#### Parts of a shaper machine :-

1. Base :-

→ The base of shaper supports the column or pillar which supports all the working parts such as ram, worktable, drive mechanism etc

→ Base is a heavy cast body.

2. Column, pillar or body :-

→ The shaper has a column which is ribbed casting of cellular construction.

→ The top of the column carries the ram sideways, the table sideways are machined on the front of the casting.

→ The crank & the geared link mechanism that drives the ram is contained within the column.

→ The driving motor, the variable speed gearbox, lever & other control of the shaper are also contained in the column.

3. Cross rail :-

→ The cross rail carries the horizontal table sideways & is mounted on the vertical guideways of the column.

→ The cross rail can be raised or lowered by means of an elevating screw in order to compensate for dust & other wear.

→ The cross rail is a heavy casting & it also carries the table cross feed screw together with the Flange & ratchet intermittent drive mechanism.

4. Saddle :-

→ Saddle is fitted to the cross rail & supports the table. If the table is removed the screw can be bolted or clamped to the T-slot in front of the saddle.

→ Crosswise movement of the saddle causes the worktable to move sideways.

5. Table :-

→ The worktable is a box shaped casting with T-slots in its upper surface & down one side. It also has a Vee machined in the vertical side to carries cylindrical work.

→ The upper surface of the worktable is machined after assembly to ensure that the working surface of the table is a true datum for work setting.

→ The worktable is bolted to the saddle & can move vertically & crosswise with the help of saddle & cross rail.

6. Ram :-

→ Ram is rigidly braced casting & is located on the top of the column.

→ The ram is driven back & forth in the slide by the slotted link mechanism.

→ The ram contains a stroke positioning mechanism & the down feed mechanism.

7. Tool head :-


→ Tool head slides in a dovetail at the front of the ram by means of T bolts.

→ It can swivel from 0° to 90° in a vertical plane.

→ The tool head can be raised or lowered by hand feed for vertical cut on the workpiece.

→ The tool head holds the tool. The tool head supports the tool, the necessary vertical, angular feed movement.

Tool head & its detail :-



The tool head & its details :-

- The tool head & its details control the infeed of the cutting tool <sup>to work</sup> of workpiece.
- In other words it controls the depth of cut & is adjusted by a feed wheel.
- The clapper box allows the cutting tool to leave on or return on <sup>feed</sup> <sup>stroke</sup>, so that tool is not dragged back through the uncut workpiece & get damaged.

Shaper size & specifications :-

- The size of shaper is classified according to the max length of stroke.
- Push-cut shapers can accept work sizes from 100 to 900 mm.
- Full-cut shapers are made for  $\phi$  work requirements upto 1.2 m.
- The max. cross feed distance is generally equivalent to the max. ram stroke distance. Therefore a shaper of 100 mm max. stroke, for example it is capable of machining a part with

a plane surface that measured at least 400 mm <sup>width</sup> <sup>400 mm square</sup>.

Specifications of a shaper :-

Max. ram stroke	700 mm
max. tool overhang	100 mm
Distance bet. table & tool	Max. 100 mm Min. 30 mm
Dimension of table w.r.t. to base	700 mm x 600 mm
Max. travel to table	Horizontal 700 mm Vertical 30 mm
Horizontal feed for double stroke	0.25 to 5 mm
principle movement motor power	4 KW
Overall dimension	2350 x 1750 x 1400 mm

2074/3 23:30



### Shaper drive mechanism :-

- A shaper drive mechanism changes the rotary motion of the power source into the reciprocating motion of the ram.
- Metal cutting is carried out during the forward stroke of the ram, the return stroke of the ram does no cutting & hence is called ideal stroke.
- Since, return stroke does no cutting, the drive is designed to incorporate a quick return mechanism so that the ram moves faster during return stroke in order to minimize the ideal time.
- Some of the shaper drive mechanism
  - a. Slotted link quick return mechanism
  - b. Whitworth's quick return mechanism
  - c. Hydraulic mechanism
- a. Slotted link quick return mechanism:-

- Slotted link mechanism is very common in mechanical shaper.
- The mechanism is simple & compact.
- It converts the rotary motion of the electric motor & gear box into the reciprocating motion of the ram.
- The slotted link mechanism gives the ram a higher velocity during the return non-cutting stroke than its forward cutting stroke thereby reducing the time covered during the return stroke.
- The Bull gear is driven by a pinion which is connected to a motor shaft through a gear box with 7.5 or more speed available.
- The Bull wheel has a slot, the crank pin 'A' is secured into the slot, at the same time it can slide in the slotted crank 'B'.
- When the bull wheel rotates, the crank pin 'A' also rotates & slides through the slot in the slotted crank 'B'.
- This makes the slotted crank to oscillate about its one end 'O'. This oscillating motion of slotted crank (through the link 'D') makes the ram to reciprocate.
- The intermediate link 'B' is necessary to accommodate the size & bar of the crank.
- The position of the crank pin 'A' in the slot in the bull wheel decides the length of the stroke of the shaper, wherever it is away from the centre of

But wheel the longer is the stroke.

- The cutting stroke of the ram is completed while the crank pin moves  $A$  to  $A_1$  & the slotted link goes from left to right. Similarly the return stroke of the crank pin moves from  $A_1$  to  $A$  & the slotted link changes its position from right to left.
- The time taken by the ideal & cutting stroke of the ram is proportional to the angle  $\angle A_1 O A$  &  $\angle A O A_1$  respectively.
- Since the crank pin  $A$  moves at a constant velocity & in a straight line, it is obvious that the ideal return stroke is quicker than the forward cutting stroke & hence the slotted link mechanism is known as "quick-return mechanism."

## \* MILLING MACHINES \*

Q.1 → How the milling machines are classified and illustrate them accordingly.

Ans - The usual classification according to the general design of the milling machines are:-

1. Column and Knee type:-

- (a) Hand milling machine
- (b) Plain milling machine.
- (c) Universal milling machine.
- (d) Omniversal milling machine.
- (e) Vertical milling machine.

2. Manufacture of box or lat type

- (a) Simple milling machine.
- (b) Duplex milling machine.
- (c) Tduplex milling machine.

3. Planer type.

4. Special type

- (a) Rotary table milling machine.
- (b) Drum milling machine.
- (c) Planetary milling machine.
- (d) Protograph, prototyping and traced controlled milling machine.

① Column and knee type:- the most commonly used is the column and knee type where the table is mounted on the knee casting which is turn is mounted on the vertical slides of the main column. The knee is vertically adjustable on the column so that the table can be moved up and down to accommodate work of various heights.

The column and knee type milling machines are classified according to the various methods of supplying power to the table, different movements of the table and different axis of rotation of the main spindle.

(a) Hand milling machine:-

The simplest of all types of milling machine is the hand miller in which the feeding movement of the table is supplied by hand control. The cutter is mounted on a horizontal arbor and is rotated by power. The machine is relatively smaller in size than that of other types and is particularly suitable for light and simple milling operations such as machining balls, grooves and key ways.

(b) Plain milling machine:-

The plain milling machines are much more rigid and stiffer than hand millers for accommodating heavy workpiece. The milling machines table may be fed by hand or power against a rotating cutter mounted on a horizontal arbor. A plain milling machine, having horizontal spindle, is also called horizontal spindle milling machine. In a plain milling machine the table may be fed in a longitudinal or vertical directions. The feed is longitudinal when the table is moved at a right angle to the spindle, it is cross when the table is moved parallel to spindle, and the feed is vertical when the table is adjusted in the vertical plane.

(c) Omniversal Milling Machine:-


In this machine the table besides having all the movements of a universal milling machine, can be tilted in a vertical plane by providing a special arrangement of the knee. Also the entire knee assembly is mounted in such a way that

it may be fed in longitudinal direction horizontally. The additional vertical arrangement of the table enables us to machine tapered grooves and in general, bevel gears etc. It is essentially a tool room and experimental shop machine.

(1) Vertical milling machine:-

A vertical mill machine can be distinguished from the horizontal milling machine by the position of its spindle which is vertical or perpendicular to the work table. The machine may be of plain or universal type and has all the movements of the table for proper setting and locating the work. The spindle which is clamped to the vertical column may be swivelled at an angle permitting the milling cutter mounted on the spindle to work on angular surfaces. In some machines, the spindle can also be adjusted up and down relative to the work. The machine is adapted for machining grooves, slots and flat surfaces. The end mills and face milling cutters are the usual tools mounted on the spindle.

1. Base
2. Saddle
3. Table
4. Spindle head
5. Column




(2) Universal milling machine:-

It is most versatile of all the milling machines, and often rather it is the most useful machine tool as it is capable of performing most of the machining operations. With its application the use of larger number of other machined tools can be avoided. It differs from the plain milling machine only in that the table can be given one more additional movement. Its table can be swivelled on the saddle in the horizontal plane. For this, circular graduations are provided on the saddle along which it can be swivelled. A graduated circular base is incorporated under the table, with a datum mark on the saddle, to readily determine the angle through which the table has been swivelled. The special feature which the work should be set at an angle with the cutter for milling helical and spiral flutes and grooves. Its over arm can be pushed back or removed and a vertical milling head can be fitted on a place of the another to use it as a vertical milling machine.

(3) Manufacturing or fixed bed type:-

The fixed bed type milling machines are comparatively large, heavy and rigid and driven vertically from column and knee type milling machines by the construction of its table mounting. The table is mounted directly on the ways of fixed bed. The table movement is restricted to reciprocate at right angles to the spindle axis within


provision for cross or vertical adjustment. The cutter mounted on the spindle heads together on a duplex machine, the spindle heads supported on one circumscribed one on each side of the table. In tripod type the third spindle is mounted on across rail. The usual feature of these machines is the automatic cycle of operation for bevelling the table, that is repeated in the regular sequence. The bevel cycle of the table includes the following stages, rapid approach, slow bevel bar cutting, rapid traverse to next workpiece, quick return and stop. This auto-matic control of the machine enables it to be used with advantage in repetitive type of work.



③ Planer Type:-

It is also called plano-miller milling machine. The plano miller, is a machine built up for heavy duty work, having spindle heads adjustable in vertical in traverse direction. It resembles a planer and like a planing

machine, it has across rail capable of being raised or lowered carrying the cutter and heads and the saddle, all supported by rigid uprights. There may be number of independent spindles carrying cutter on the rail as well as two heads on the upright. This arrangement of independently multiple cutter spindles enables number of work surfaces to be machined simultaneously. There by obviating



great reduction in production time. The elevated clearance bed in a planer and plano-miller in the table movement. In a planer, the table moves to give the cutting speed, but in a plano-milling machine the table movement gives the bevel. Hence the table movement in a plano-milling machine is much slower than that of a planing machine. Standar plano miller are provided with higher power driven spindles powered to the extent of 100 h.p. and the rate of metal removal is tremendous. The use of the machine is limited to production work only and is considered ultimate in metal removing capacity.

④ Special Type:- Milling machines of non-con-

Special designs have been developed to suit special purpose. The features that they have in common are the spindle for rotating the cutter and provision for moving the tool on the work in different directions. The following special type of table machines of interest are observed below:-

(a) Rotary table Machine:-

The construction of the machine is a modification to a vertical milling machine and is adapted for machining flat surfaces at production rate. The face milling cutter are mounted on two or more vertical machine spindles and a number of work pieces are clamped on the horizontal surface of a circular table which rotate about a vertical axis. The cutters may be set different height relative to the work so that when one of the cutter is roughing the pieces, the other is finishing them.

(b) Drum milling machine:-

The drum milling machine is similar to a rotary table milling machine is that its work supporting table, which is called a drum, rotates on a horizontal axis. The face milling cutters mounted on three or four spindle heads rotate in horizontal axis and remove metal from workpiece presented on both the face of the drum. The

finished machined parts are removed after one complete turn of the drum, and then the new ones are clamped to it.

(c) Planetary milling machine:-

In a planetary milling machine, the work is held stationary while the revolving cutter or cutters move in a planetary path to finish a cylindrical surface on the work either in a turnally or circumferentially. The machine is particularly adapted for milling internal or external threads of different pitches.

(d) Pantograph milling machine

A pantograph machine can duplicate a job by using a pantograph mechanism which permits the size of the workpiece reproduced to be smaller than, equal to or greater than the size of a template or model used for the purpose. A pantograph is a mechanism that is generally constructed of four bars or links which are joined in the form of a parallelogram. Pantograph machines are available in two dimensional or three dimensional models. Two dimensional pantograph is used for engraving letters or other designs, where as three dimensional models are employed for copying and shape and contour of the workpiece.

(e) Milling machine:- A pantograph machine duplicates the full size of the template attached to the